



MALLORY

REPLACEMENT VIBRATORS

U. S. LETTERS PATENT NO. 1,943,240

OTHER PATENTS PENDING

for ALL popular
AUTO RADIO RECEIVERS

April 15, 1936

MALLORY REPLACEMENT VIBRATOR CHART FOR ALL POPULAR AUTO RADIO RECEIVERS

Prices subject to change without notice . . . If the unit you require is not listed, write for further information

*Requires Special Cup Adapter. Supplied with Vibrator at \$5.00 list, or separately at \$1.00 list.

The prefix letter "F" designates Vibrator designed for 32-volt service. The prefix letter "G" designates Vibrator designed for 12-volt Service.

Mallory Replacement Vibrator Chart for all Popular Auto Radio Receivers

Prices subject to change without notice . . . If the unit you require is not listed, write for further information

Name of Set	Model Number	Correct Mallory Replace- ment Vibrator Number	List Price
Trav-ler	54, 64	294	\$4.50
Tropic-Aire—See Wells-Gardner.			
Troy	TR-86	296	4.50
True-tone—See Western Auto.			
Truevalue	.6U	253	4.50
United American			
Bosch	524A-634-634A	253Y	4.50
140 (Ed. 2 & 3)	271		5.50
150 (Edition 1)	219		5.75
150 (Edition 2)	271		5.50
160	271		5.50
45A, 45C	271		5.50
79	253		4.50
536, 636, 637, 736, 737, 738	294		4.50

United Motors Service			
Buick-Olds-Pontiac.	393884-393885	273C	5.50
405045-405046	273C		5.50
405057	273C		5.50
405062-405063	273C		5.50
544245-544246	273C		5.50
544267-544268-544289-			
544290-544291-544297-			
544298	273C		5.50
980393	221		4.75
980441	222		5.25
980455-980459	222		5.25
980507-980508	273D		5.50
980509, 980525	273D		5.50
982006-982007	273C		5.50
982008	273C		5.50
983506-983507	273C		5.50
1291344-1291345	273C		5.50

Chevrolet			
364441	221		4.75
600153-600566	222		5.25
600249-600565	222		5.25
601038	273C		5.50
601176-601177	273C		5.50
601525, 601574	273C		5.50
601586	273C		5.50
601662, 601814	273C		5.50
985100-985200	294		4.50
985300	273D		5.50
985400	273C		5.50
Delco	626, 627, 628, 629, 634, 635	273C	5.50
630, 631, 632, 633, 500	294		5.50
2035, 4036	221		4.75
4037, 4038	222		5.25

Utah	"B" Eliminator Non-syn- chronous	221	4.75
Wells-Gardner	V6Z2†	292	4.50
	Z6Z1†	292	4.50

Name of Set	Model Number	Correct Mallory Replace- ment Vibrator Number	List Price
Wells-Gardner	25Y1	286S	\$5.50
(continued)	25Y1-12 volt	G286S	6.50
	062-062A	206	5.00
	072-072A	211	5.75
	06W (1st Series)	210	5.75
	06W (2d Series)	237	5.75
	26U1 (6U)	253	4.50
	26S1 (6S)	253	4.50
	06X	210	5.75
	6R	253	4.50
	6N	294	4.50

Name of Set	Model Number	Correct Mallory Replace- ment Vibrator Number	List Price
Western Auto	S-732 (Z6Z1)†	292	4.50
(True-tone)	S-733, (V6Z2)†	292	4.50
	S-690, (062), S-691, (062-A)	206	5.00
	S-740 (6U)	253	4.50
	S-735 (25Y1)	286S	5.50
	S-743, 1312 (R-131)	294	4.50
	670 (6S)	253	4.50

Name of Set	Model Number	Correct Mallory Replace- ment Vibrator Number	List Price
Westinghouse	WR-25, WR-26	294	4.50
	4-prong Socket	296	4.50
	6-prong Socket	253Y	4.50
	WR-500-501	253Y	4.50

Name of Set	Model Number	Correct Mallory Replace- ment Vibrator Number	List Price
Westinghouse	A43, A44	273*	5.50
(Canada)			
Wilcox-Gay	4B6, Roadmate	292	4.50
Wurlitzer	460-A60	292	4.50
Zenith	7	296	4.50
	460-462 (2057)	292	4.50
	650HD-651HE	292	4.50
	660TD-661TE	292	4.50
	Ford	296	4.50
	666, 668, 680	294	4.50

6-VOLT HOUSEHOLD RECEIVERS			
Addison	N-655	285XS	\$6.00
Crosley	6615, 435	246	5.50
Delco	6010	281	5.50
Knight	(Chassis 6820)	285XS	6.00
LeWol	9682	285XS	6.00
Lafayette	160	285XS	6.00
Pacific	682	285XS	6.00
L'Tatro	6A, K665, J665, H465, I465, 275	5.50	
	R5236, Q5363, P4626, Q4626		
	M4616 All 1st Series	275XS	6.00
	R5236, Q5363, P4626, Q4626		
	M4616, All 2d Series	285XS	6.00
Zenith	4V31, 4V59, 6V27, 6V62	246	5.50

Name of Set	Model Number	Correct Mallory Replace- ment Vibrator Number	List Price
-------------	--------------	--	---------------

32-VOLT HOUSEHOLD RECEIVERS

Name of Set	Model Number	Correct Mallory Replace- ment Vibrator Number	List Price
Atwater Kent	135Z, 215Z	F297	\$5.50
Crosley	119, 159	F223	6.75
Delco	4050, 4051	F223	6.75
	3203	F247	6.50
Erla-Sentinel	5600	F253	5.25
	6101	F292	5.50
Fairbanks-Morse	33-S-8 (1st Series)	F312	6.00
	33-S-8 (2d Series)	F221	5.75
Lafayette	B64	F253	5.25
Majestic	490, 491, 493 (Transformer Type)	F220C	6.00
	490, 491, 493 (Plug-in Type)	F294	5.50

Name of Set	Model Number	Correct Mallory Replace- ment Vibrator Number	List Price
Montgomery-Ward (Airline)	62-136, 62-138	F253	5.25
Simplex	P	F221	5.75
L'Tatro	Admiral F293	F204	5.00
	Captain F913	F204	5.00
	Commander E33	F204	5.00
	Governor N54	F211	6.25
	Governor N74	F251	5.25
	Lt. Governor L54	F211	6.25
	Lt. Governor L74	F251	5.25
	Pilot J5, G63	F204	5.00
	President 084	F211	6.25
	President 094	F251	5.25
	F725, D625, C625	F251	5.25
	Recorder P54	F251	5.25
	Recorder P64	F251	5.25
	X6236, W6236, V5226, U5226, T6216	F251	5.25
Wells-Gardner	26B1, 26B5	F253	5.25

*Requires Special Cup Adapter. Supplied with Vibrator at \$.50 list, or separately at \$1.00 list.

†CAUTION! If the vibrator being replaced in one of these radio sets is a DeVry Carbon Point Vibrator, it will be necessary to replace the power transformer with one of a later type. This transformer is available from the Radio Set Manufacturer.

The prefix letter "F" designates Vibrator designed for 32-volt Service. The prefix letter "G" designates Vibrator designed for 12-volt Service.

